

312 BG Universal Synthetic ATF

APPLICATION CHART

BG Universal Synthetic ATF, PN 312, meets or exceeds the performance requirements of the following automatic transmission fluids.

MAKE	ATF PN
Acura	ATF-Z1, DW-1, TYPE 3.0 PN 08200-9016A, TYPE 2.0 PN 082009015A, TYPE 3.1 PN 08200-9017A
Aisin Warner	AW-1, AS69RC, 05189966AB, 05189977AA
Alfa Romeo	ALL
Allison	C-3, C-4, John Deere HD SynTran, TM Mobil Delvac Synthetic ATF TM
American Motors	ALL
Aston Martin	ALL
Audi	G052025A2, G052162A1, G052162A2, LT71141, G055025A2, G055005A2, G055162A2, G060162A2, G055005A6, G052990A2, G055540A2
Bentley	ALL INCLUDING PY112995PA
BMW	LA2634, LT71141, 81229400275, 83220142156, 83220403248, 83220403249, 83229407765, 83229407807, 83220024359, 83220026922, BMW807, TEXACO ETL-7045E, TEXACO ELT-8072B, 83220142516, 705/ATFD-3, 83220402413, 83220397114, 83222152426, 83227542290, 83222163514, 83222220445 (1375.4), 83222289720
Caterpillar	TO-2
Chrysler/Mopar	ATF 7176, +2, +3 (MS-7176E), +4 (MS-9602), AS68RC, AS69RC, 05127382AB, 05189966AB, 05189966AA, 05189977AA, 05127382AA, 68157995AA, 68157995AB, 68218925AA, 68171866, 68171869AB
Citroen	973622, Z000169756
Daewoo	ALL INCLUDING LT71141
Diwa	ALL
Esso	ATF LT 71141
Fiat-Lancia	ALL
Ford	MERCON [®] (XT-2-QDR OR XT-2-QSM), MERCON [®] SP (XT-6-QSP), MERCON [®] V (XT-5-QM), MERCON [®] LV(XT-10-QLV), PREMIUM AUTOMATIC TRANSMISSION FLUID (XT-8-QAW), FNR5 AUTOMATIC TRANSMISSION FLUID (XT-9-QMM5), X-2-QDX
Fuchs	Titan ATF 3292, Titan ATF 3353
General Motors	DEXRON [®] , DEXRON [®] -II, -IID, -IIE, -III, -IIIG/H, DEXRON [®] -VI, GM T-IV (PN 88900925), 9986195
Honda	ATF-Z1, DW-1, TYPE 3.1 08200-9017
Hyundai	SP-II, SP-III, SPH-IV (00232-19045), 040000C90SG, NWS-9638, SPH-IV-RR, 00232-19012, 00232-19015, 00232-19016, 00232-19023, 00232-19024, SP4-M, JWS-3309 T-4, 00232-19057, 00232-19059, NWS-9638 T5
Idemitsu	K17, JATCO 3100 PL085, W0133-19031-54
Infiniti	ALL INCLUDING MATIC D, J, K, S
Isuzu	ALL
Jaguar	ATF 3403 M115, C2C8432, 1X43 2C9010AA, JLM 20237, JLM 20238, LT71141, JATCO 3100 PL085, JDE 26444
JASO	1A
Jeep	SEE CHRYSLER/MOPAR
JWS	3309, 3314, 3317, 3324

MAKE ATF PN

Kia	SP-II, SP-III, RED 1, SP IV, UM090-CH042 (TYPE 4 SP-IV), ATF TYPE 4(M)
Land Rover	ESSO LT71141, TEXACO N402, TYK500050, LRN 13754, TEXACO ETL-7045E, STC 4863, STC 505.31, LR 002748, LR 023288, LR 023289
Lexus	ALL
Man	339F, 339V1, 339V2, 339Z1, 339Z2, 339Z3
Maserati	231603
Matra	ALL
Mazda	ATF-M III, ATF-MV, ATF-FZ, 0000-77-112E-01, 0000-77-120E-05, 0000-77-114E-01, 0000-FZ-113E-01
Mercedes Benz	236.1, 236.2, 236.3, 236.5, 236.6, 236.7, 236.8, 236.9, 236.10, 236.11, 236.12, 236.14, 236.41, 236.81, 0019892103, SHELL 3403-4 115, A0019892203, 0019894503, ATF 4134, 0019896803
Mitsubishi	DIAMOND SP, SP-II, SP-III, SP-IV, J2, J3
Nissan	MATIC D, J, K, S, 402
Opel	ALL
Peugeot	973622, Z000169756
Porsche	99991754700A2, 00004320509, 00004320441, SHELL 3403 M115, 99991754700, 000 043 205 28
Renault	7711218368
Rolls Royce	PL31493 PA
Saab	93160372, 93160393, 93165147
Saturn	22689186, ALL
Shell	LA2634, ATF 3353, ATF 3403, M115, M-1375.4, M-1375.5, M-1375.6, M-L12108
Subaru	SOA868V9241, K0140Y0700, ATF-HP, HP/PS (SOA427V1500 HP), ALL
Suzuki	99980-06000, ATF 3317 SP-4B, 990B0B-01001, 3314, ALL
Texaco	ETL-7045E, ETL-8072B, N402
Toyota	TYPE T, T-II, T-III, TYPE T-IV, TOYOTA WS
Voith	55.6335.XX (G607), 55.6336.XX (G1363)
Volvo	97340, 97341, 97342, 3344208, 31256774, 31256775, 31256776, 1161521, 1161540, 1161640, 1161621,
Volkswagen	G055025A2, G055162A2, G052162A2, G052990A2, G052025A2, G052162A1, G055005A6, LT71141, G055005A2, G060162A2, G055540A2
ZF Friedrichshafen AG	TE-ML: 02F, 03D, 04D, 05L, 09, 11A, 11B, 14A, 14B, 14C, 16L, 17C, SHELL LA 2634, LT 71141, LifeGuard Fluid 6 (S671090255), LifeGuard Fluid 6 Plus (S671090281), LifeGuard Fluid 8 (AA00601304, S671090312)

BG Universal Synthetic ATF is not recommended for use in the following applications:

Continuously Variable Transmissions (CVTs)

Dual Clutch Transmissions (DCT)

Direct-Shift Gearbox (DSG)

Ford Type F

GM DEXRON®-HP

All Mercedes Benz 722.9 transmissions built after June 21, 2010 requiring ATF A0019897803 (236.15)

BG Products, Inc., accepts no liability for excessive use or misuse of this product.

Revision date 1-19-17

Revisions **Added to BMW section**
- 83222289720

1-19-17 **Added to Land Rover section**
- LR 023289

12-9-16 **Revised Ford and GM sections**
- Removed spaces after MERCON®
- Added hyphens after DEXRON®

10-20-16 **Added to Acura**
- TYPE 3.1 PN 08200-9017A

8-23-16 **Added to Acura**
- TYPE 2.0 PN 082009015A

5-5-16 **Added to Not Recommended section**
- GM Dexron HP

4-28-16 **Added to Land Rover:**
- LR 023288

3-17-16 **Added to Chrysler/Mopar:**
- 68171869AB

Added to Honda:
- TYPE 3.1 08200-9017

1-25-16 **Added to Aisin Warner**
- AS69RC, 05189966AB, 05189977AA

Added to Chrysler/Mopar
- AS69RC, 05189966AB

1-5-16 **Added to Acura**
- TYPE 3.0 PN 08200-9016A

Added to BMW
- 83222220445 (1375.4)

- 7-20-15 Added to Land Rover:**
- LR 023288
- 7-13-15 Changed Acura:**
- REMOVED "ALL" ADDED "ATF-Z1, DW-1"
- Added to Fuchs:**
- Titan ATF 3353
- Added to Hyundai:**
- 00232-19057, 00232-19059
- Removed from Hyundai:**
- T-5
- Added to Mercedes Benz:**
- 236.41, 236.81
- 6-25-15 Added to Allison:**
- John Deere HD SynTran™
- Mobil Delvac Synthetic ATF™
- 5-18-15 Added this PN to Chrysler/Mopar:**
- 68171866
- 3-27-15 Added this PN to Kia:**
- ATF TYPE 4(M)
- 3-9-15 Added "(S671090312)" to LifeGuard Fluid 8**
under ZF Friedrichshafen AG
- 10-28-14 Removed "ALL" from Jeep. Replaced with:**
- See Chrysler/Mopar
- 10-1-14 Added this ATF PN from Chrysler/Mopar:**
- 68218925AA
- Added this ATF PN from Fuchs:**
- Titan ATF 3292
- 9-3-14 Removed these ATF PN's from Allison:**
- TES-295
- TES-389

8-28-14 Added these ATF PN's to Volvo:

- 31256775
- 31256776

8-13-14 Added these ATF PN's to Mazda:

- ATF-FZ
- 0000-FZ-113E-01

6-12-14 Added this ATF PN to Subaru:

- HP/PS (SOA427V1500 HP)